

Supplemental Type Certificate

Number SR01865LA

This Certificate issued to LifePort, Inc.
1610 Heritage Street
Woodland, Washington 98674

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 27 of the Federal Aviation Regulations. *Certification basis is set forth in Type Certificate Data Sheet H9EU*

Original Product Type Certificate Number: H7EU

Make: AGUSTA

Model: Model A109E, Model A119

Description of Type Design Change: Installation of an Emergency Medical Rescue Stretcher in accordance with FAA approved Master Drawing List for the Emergency Medical Rescue Stretcher Installation in the AGUSTA A109E & A119 Helicopter, MDL-813-00, Revision G, dated April 3, 2006 or later FAA approved revision. FAA approved Rotorcraft Flight Manual Supplement No. EGR-813-11, dated March 31, 2006, or later FAA approved revision is required as part of this installation.

Limitations and Conditions: The installation should not be incorporated in any aircraft unless it is determined that the interrelationship between this installation and any previously approved configuration will not introduce any adverse effect upon the airworthiness of the aircraft. The approval of this modification applies to the above noted airplane model series only. A copy of this STC must be included in the permanent records of the modified aircraft. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: April 19, 2005

Date reissued:

Date of issuance: April 6, 2006

Date amended:



By direction of the Administrator

Original signed by Michael O'Neil

(Signature)

Manager, Airframe Branch
Los Angeles Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.