

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number SA1005NE

This certificate issued to Aerosonic Corporation
1212 North Hercules Avenue
Clearwater, FL 33765

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 23 of the Federal Aviation Regulations.

Original Product Type Certificate Number: A25CE

Make: Cessna Aircraft Company

Model: 404

Description of Type Design Change:

Installation of Teledyne Avionics Power Analyzer and Recorder (PAR) Part No. SL17052 in accordance with the data contained in Teledyne Avionics Installation Manual No. 17052IM.001, dated April 1, 1992.

Limitations and Conditions:

1. Teledyne Avionics "Airplane Flight Manual Supplement for Cessna Model 404 Aircraft with Titan Aerospace STC No. SA5929SW", FAA approved September 12, 1992 is required with this installation.
2. Eligibility restricted to aircraft incorporating STC SA5929SW.
3. Teledyne Avionics "Operators Manual Power Analyzer and Recorder (PAR)", Document No. 1705200M, dated April 1, 1992 must accompany each installation.
4. The Installer must determine whether this design change is compatible with previously approved modifications.
5. If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: April 1, 1992

Date reissued: March 8, 1993, August 14, 2007

Date of issuance: September 14, 1992

Date amended:

By direction of the Administrator



(Signature)

Anthony Socias
Manager
New York Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.