

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number SH2348SW

This certificate issued to Scott's-Bell 47, Inc.
100 Minnesota Avenue
Le Sueur, MN 56058

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 6 of the Civil Air Regulations.

Original Product--Type Certificate Number : H-1, 2H3, H5SW

Make : Bell Helicopter Textron; Continental Copters, Inc.

Model : 47G-2, 47G-2A, 47G-2A-1, 47G-3B, 47G-3B-1, 47G-3B-2, 47G-4, 47G-4A, OH-13H/Mark 5A, OH-13H/Mark 6C

Description of Type Design Change:

Installation of Sprag System Kit P/N 74-612-153-1M Revision D, dated 9/17/14, according to 74-612-153-INS Installation Instructions Revision C, dated 9/23/2014 or later FAA-approved revisions.

Limitations and Conditions:

1. Also eligible for installation of OH-13H/Tomcat Mark 6C, STC SH1878SW modification to H5SW Type Certificate.
2. The installer must determine whether this design change is compatible with previously approved modifications.
3. If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission.

This certificate and the supporting data, which is the basis for approval, shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : August 04, 1976

Date of issuance : August 13, 1976

Date reissued : March 04, 1986; July 27, 1987;
April 30, 2004; December 15, 2010; August 07, 2014;
August 26, 2015

Date amended : November 30, 1976; June 17, 1978;
October 13, 1978; October 23, 1980 Rev. 4

By direction of the Administrator
Original Signed By:
Manzoor Javed for

(Signature)

Karol Mordasiewicz
Manager, Airframe and Administrative Branch
Chicago Aircraft Certification Office

(Title)



Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.