

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number SA188CE

This certificate issued to

Ontic Engineering and Manufacturing Inc.
20400 Plummer Street
Chatsworth, CA 91311

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 3 of the Civil Air Regulations. (See Type Certificate Data Sheet No. 3A20 for Complete certification basis)

Original Product--Type Certificate Number: 3A20

Make: Raytheon Aircraft Company

Model: 65, 65-80, and 65-A80

Description of Type Design Change:

Install twin-engine synchronizer in accordance with Installation Manual for Woodward Electronic Synchronizer Kit for Beech model 65, Dated December 5, 1963 and Drawing 213046 dated 11/6/1963 or Installation Manual for Woodward Electronic Synchronizer Kit for Beech model 65-80, Bulletin 33028 Dated June 15, 1964 and drawing 213189, dated May 13, 1964 or later FAA approved revision.

Limitations and Conditions:

1. Woodward Airplane Flight Manual Supplement dated December 20, 1963 for Beech Model 65 or Woodward Airplane Flight Manual Supplement dated July 15, 1964 for Beech Models 65, 65-80 and 65-A80 or later FAA approved revision is required.
2. Compatibility of this design change with previous modifications must be determined by the installer.
3. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: December 5, 1963

Date reissued: September 30, 2005, April 30, 2007

Date of issuance: December 20, 1963

Date amended: July 15, 1964

By direction of the Administrator



(Signature)

Thomas A. Enyart
Manager, Propulsion Branch
Los Angeles Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.