

United States Of America
Department of Transportation - Federal Aviation Administration
Supplemental Type Certificate

Number **SR01860LA**

This Certificate issued to Diamond J, Inc.
2020 West Harry
Wichita, KS 67213

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 27 of the Federal Aviation Regulations. *Certification basis is set forth in Type Certificate Data Sheet H9EU*

Original Product Type Certificate Number: H9EU

Make: Eurocopter

Model: AS350 B2

Description of Type Design Change: Installation of a new exhaust gas temperature (EGT) indicator to replace the current EGT indicator. This installation must be performed in accordance with FAA Approved Diamond J, Inc. Installation Instructions Drawing Number 87153, Rev. IR, dated November 12, 2005, or later FAA approved revisions.

Limitations and Conditions: The installation should not be incorporated in any rotorcraft unless it is determined that the interrelationship between this installation and any previously approved configuration will not introduce any adverse effect upon the airworthiness of the rotorcraft. The approval of this modification applies to the above-noted rotorcraft model series only. A copy of this STC must be included in the permanent records of the modified rotorcraft. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: September 19, 2005

Date reissued:

Date of issuance: January 18, 2006

Date amended:

By direction of the Administrator



(Signature)

Manager, Propulsion Branch
Los Angeles Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.