

Department of Transportation - Federal Aviation Administration

Supplemental Type Certificate

Number SA5903NM

This certificate, issued to

**KNOTS 2U, LTD
709 Airport Road
Burlington, WI 53105**

*certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part * of the * Regulations.*

Original Product—Type Certificate Number: * See attached Approved Model List (AML)

Make: * No. SA5903NM for a list of approved

Model: * airplane models and applicable airworthiness regulations.

Description of the Type Design Change: Fabrication of Model RMD-00035-B replacement wings-tips with supplemental landing and recognition lights in accordance with Drawing List No. RMD-3536 MDL, dated April 1, 1992, or later Federal Aviation Administration (FAA) approved revision, and Installation of these replacement wing-tips in accordance with Installation Instructions RMD-3536-II, dated April 1, 1992, or later FAA approved revision.

Limitations and Conditions: Approval of this change in type design applies to only those Beech airplane Models listed on AML No. SA5903NM, dated December 21, 1992, or later FAA-approved revision, which were previously equipped with Beech wing station 191 rib assemblies Part No. 35-115031 (LH) and 35-115031-1 (RH). This approval should not be extended to aircraft of these models on which other previously approved modifications are incorporated unless it is determined that the relationship between this change and any of those other previously approved modifications, including changes in type design, will introduce no adverse effect upon the airworthiness of that aircraft. A copy of this Certificate, Continuation Sheet No. SA5903NM and AML No. SA5903NM must be maintained as part of the permanent records for the modified aircraft (See Continuation Sheet page 3 of 3).

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: February 21, 1992

Date reissued: October 9, 2015

Date of issuance: December 21, 1992

Date amended:



By direction of the Administrator

(Signature)

Manager, Seattle Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.

Supplemental Type Certificate

(Continuation Sheet)

Number SA5903NM

KNOTS 2U, LTD

Issued: December 21, 1992

Reissued: October 9, 2015

Limitations and Conditions continued:

A set of the wing-tip position lights listed below must be installed with this wing-tip replacement installation:

Grimes P/N A-1285G-12 and A-1285R-12, or
P/N A-1285G-24 and A-1285R-24

Whelen P/N W1285-PG-14 and W1285-PR-14, or
P/N W1285-PG-28 and W1285-PR-28

- END -

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.