

Supplemental Type Certificate

Number SA10284SC

This certificate, issued to

**Eagle Creek Aviation Services
4101 Dandy Trail
Indianapolis, IN 46254**

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 3 of the Civil Air Regulations

<i>Original Product—Type Certificate Number:</i>	2A4
<i>Make:</i>	Twin Commander
<i>Model:</i>	690; 690A; 690B; 690C; 690D; 695; 695A; 695B

Description of the Type Design Change: Installation of right side Meggitt EFIS, i.e. Primary Flight Display (PFD), Navigation Display (ND), and Air Data Attitude Heading Reference System (ADAHRS) in accordance with Twin Commander Aircraft Master Drawing List No. 800829, Rev. B, dated September 14, 2004 or later FAA approved revision. FAA approved Airplane Flight Manual Supplement Document No. MEGGITT-3, Rev. I.R., dated September 22, 2004, or later FAA approved revision is required.

Limitations and Conditions: Compatibility of this design change with previously approved modifications must be determined by the installer. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

See Continuation Sheet – Page 3

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

<i>Date of application:</i>	April 5, 2004	<i>Date reissued:</i>	July 9, 2007
<i>Date of issuance:</i>	October 8, 2004	<i>Date amended:</i>	



By direction of the Administrator

____ Original signed by Angelos Xidias ____
(Signature)
 Acting Manager, Seattle Aircraft
 Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.

Supplemental Type Certificate

(Continuation Sheet)

Number **SA10284SC**

Eagle Creek Aviation Services

Reissued: July 9, 2007

Amended:

Limitations and Conditions: (cont'd)

Regulations at the latest amendments 23-0 through 23-55, 23.29, 23.301, 23.303, 23.305, 23.307, 23.321, 23.331, 23.333, 23.335, 23.337, 23.341, 23.561, 23.601, 23.603, 23.605, 23.609, 23.611, 23.613, 23.771 (a), 23.867, 23.1301 (a, b, c, d), 23.1303 (a, b, c, f), 23.1307, 23.1309, 23.1311, 23.1321, 23.1322, 23.1323 (a, c), 23.1325 (a, b), 23.1327 (a, f), 23.1331, 23.1335, 23.1351 (a, b), 23.1353 (h), 23.1357 (a-d), 23.1359 (c), 23.1365 (a, b, d-f), 23.1367 (a, b, c, d), 23.1381, 23.1431 (a, b), 23.1501, 23.1529, 23.1541 (a2), 23.1543, 23.1545 (a, b4, d), 23.1581, 23.1585 (a).

- END -

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.
