

United States of America
Department of Transportation — Federal Aviation Administration
Supplemental Type Certificate

Number SA898NW

This certificate, issued to Seattle Flight Service, Inc.

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 3 of the Civil Air Regulations.

Original Product — Type Certificate Number: 3A15
Make: Beech
Model: A36

Description of Type Design Change: Installation of B. F. Goodrich de-icing boots on the Hartzell HC-F3YR-1RF/F8468AB-8Q propeller in accordance with B. F. Goodrich Installation Manual Report Number 70-04-700A.

Limitations and Conditions: Data pertaining to this modification are considered inadequate for duplication in other aircraft. This approval is limited to the installation in Beech A36, Serial Number E-612 only. A copy of this Certificate and FAA Approved Airplane Flight Manual Supplement shall be maintained as a part of the permanent records for the modified aircraft.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: February 26, 1980

Date reissued:

Date of issuance: February 28, 1980

Date amended:



By direction of the Administrator
Charles C. Schroeder
(Signature)

Chief, Engineering and Manufacturing Branch
(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.