

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate
IMPORT

Number SA02638NY

This certificate issued to Aero Consulting Services Ltd.
25 Dunlop Avenue
Winnipeg, Manitoba
Canada R2X 2V2

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 23 of the Federal Aviation Regulations.

Original Product -- Type Certificate Number: A78EU

Make: Pilatus

Model: PC-12/45

Description of Type Design Change:

Belly Pod to be installed in accordance with Aero Consulting Services Ltd. Modification Summary E789000, Revision C, dated November 24, 2008, or later Transport Canada approved revision.

Limitations and Conditions:

1. FAA STC SA02377NY and SA02351NY must be incorporated prior to the incorporation of this installation.
2. This installation is limited to PC-12/45 aircraft, serial number 101 - 683, with the pre-AIM (Aerodynamic Improvement Modification) configuration.
3. With the Belly Pod installed, per installation configuration E636117-3, the aircraft is to be limited to the Restricted Category only, as compliance to 14 CFR 23.1303(e) Amdt. 23-17 and 23.1545(d) Amdt. 23-23 has not been shown.

(See Continuation Sheet 2 of 2)

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: August 22, 2007

Date reissued:

Date of issuance: January 6, 2009

Date amended:

By direction of the Administrator



(Signature)

Anthony Socias
Manager
New York Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

United States of America
Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate

(Continuation Sheet)

IMPORT

Number SA02638NY

Limitations and Conditions (Continued):

4. Maintenance must be in accordance with Aero Consulting Services Ltd. Aircraft Maintenance Manual Supplement E789070, Revision N/C, dated July 18, 2007, or later Transport Canada accepted revision.
5. Operation must be in accordance with Aero Consulting Services Ltd. Airplane Flight Manual Supplement E789090, Revision A, dated September 25, 2008, or later Transport Canada approved revision.
6. The installer must determine whether this design change is compatible with previously approved modifications.
7. If the holder agrees to permit another person to use the certificate to alter a product, the holder must give the other person written evidence of that permission.

---END---