

Supplemental Type Certificate

Number SR01592SE

This certificate, issued to Heli-Trade Corporation
90451 Boeing Drive
Eugene, OR 97402

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part * of the * Regulations.

Original Product—Type Certificate Number: * See attached FAA Approved Model list (AML)

Make: No. SR01592SE for a list of approved rotorcraft

Model: models and applicable airworthiness

regulations.

Description of the Type Design Change: Installation and Maintenance of Goodrich Internal Rescue Hoist, in accordance with Heli-Trade Master Drawing List HT-415-MDL, Revision IR, dated August 10, 2005, or later FAA approved revisions.

Limitations and Conditions: Approval of this change in type design applies to the above rotorcraft only. This approval should not be extended to other rotorcraft on which other previously approved modifications are incorporated unless it is determined that the relationship between this change and any other previously approved modifications, including changes in type design, will introduce no adverse effect upon the airworthiness of that rotorcraft. Rotorcraft modified in accordance with this STC, must be operated in accordance with the FAA approved copy of the Rotorcraft Flight Manual Supplement, Document FMS-415-29.1581, FAA Approved August 12, 2005. A copy of this Certificate must be maintained as part of the permanent records for the modified rotorcraft.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission. (See Continuation Sheet page 3.)

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: February 25, 2005

Date reissued:

Date of issuance: August 22, 2005

Date amended: November 15, 2005

By direction of the Administrator



(Signature)

Acting Manager, Seattle Rotorcraft
Certification Office

(Title)

UnitedStatesofAmerica

DepartmentofTransportation_FederalAviationAdministration

Supplemental Type Certificate

(Continuation Sheet)

Number SR01592SE

Issued to: Heli-Trade Corporation

Date of Issuance August 22, 2005

Date Amended: November 15, 2005

Limitations and Conditions: (cont'd)

In order to operate the internal hoist kit in the referenced airframes, the following provision kits must be installed:

Hoist Part Number	Bell Provision Kit	Bell Service Instruction	Rotorcraft	S/N Effectivity
HTC-42305A	205-706-091-1	BHT-205-SI-44	205A-1	30001-30228
HTC-42305A	205-706-091-1	BHT-205-SI-44	205B	30351 and Sub.
HTC-42305A	205-706-091-101	BHT-205-SI-44	205A-1	30229-30350
HTC-42305A	212-706-013-11	BHT-212-SI-85	212	30680-31311
HTC-42305A	212-706-013-11	BHT-212-SI-85	212	35001-35010
HTC-42305A	212-706-013-103	BHT-212-SI-85	212	35011 and Sub.
HTC-42305A	214-706-013-1	BHT-214-SI-1	214ST	28201 and Sub.
HTC-42305A	412-706-011-105	BHT-412-SI-32	412	33001 and Sub.