

Supplemental Type Certificate

Number SR00788DE

This certificate, issued to Billings Flying Service, Inc.
6309 Jellison Road
Billings, Montana 59101

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 21 of the Federal Aviation Regulations.*

*Certification basis is set forth in Type Certificate Data Sheet R0011DE

Original Product—Type Certificate Number: R0011DE

Make: Billings Flying Service, Inc.

Model: BFS CH-47D

Description of the Type Design Change:

Installation of Bubble Windows on BFS CH-47D Chinook Rotorcraft for Left and Right sides of the Pilot and Co-Pilot doors respectively in accordance with Bubble Window Mod CH-47 Drawing BFS-003-002, Revision D, dated April 15, 2015 or later FAA approved revision.

Limitations and Conditions:

This installation should not be incorporated in any rotorcraft unless it is determined that the interrelationship between this installation and any previously approved configuration will not introduce any adverse effect upon the airworthiness of that aircraft. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission. FAA approved Flight Manual Supplement, Report Number BFS-210-101, Rev. Original, dated June 23, 2015 or later FAA approved revision must be provided with this STC. Instructions For Continued Airworthiness, Report BFS-202-101, Revision 0, dated March 23, 2015, or later FAA accepted revision must be provided and maintained as a part of the permanent records for this aircraft.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: September 22, 2014

Date reissued:

Date of issuance: July 14, 2015

Date amended:



By direction of the Administrator

Gregory Johnson (Program Manager) (Signature)
Northwest Mountain Regional Manager
Denver Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.