

United States of America
Department of Transportation — Federal Aviation Administration
Supplemental Type Certificate

Number SA6070NM

This certificate, issued to ALDEN ENGINEERING
52 Country Club Gate
Pacific Grove, California 93960

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part * of the * Regulations. *

Original Product — Type Certificate Number: * *See attached FAA Approved Model List (AML) to SA6070NM for list of approved models and applicable airworthiness regulations
Make: *
Model: *

Description of Type Design Change:

Installation of a "quick-disconnect drain plug" on the engine rocker sump for the oil drain retrieval system after engine shut-down, in accordance with Alden Engineering Installation Instructions as listed on AML No. SA6070NM, or later FAA approved revision.

Limitations and Conditions: Approval of this change in type design applies to the above model aircraft only. This approval should not be extended to aircraft of this model on which other previously approved modifications are incorporated unless it is determined that the relationship between this change and any of those other previously approved modifications, including changes in type design, will introduce no adverse effect upon the airworthiness of that aircraft. A copy of this Certificate and FAA Approved Model List (AML) No. SA6070NM amended October 19, 1993, or later Approved revision, must be maintained as part of the permanent records for the modified aircraft.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: October 13, 1993

Date of issuance: October 20, 1993

Date issued:

Date amended:

By *[Signature]* of the Administrator

(Signature)

Manager, Propulsion Branch
Los Angeles Aircraft Certification Office

(Title)



Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.