

United States of America
Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate

IMPORT

Number ST02531NY

This certificate issued to Bombardier, Inc.
200 Chemin Cote Vertu Ouest
Dorval, Quebec
Canada H4S 2A3

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.

Original Product -- Type Certificate Number: T00003NY

Make: Bombardier

Model: BD-700-1A10 and BD-700-1A11

Description of Type Design Change:

Window Plug to be installed in accordance with Aero Consulting Services Modification Data Summary Number F338000, Revision B, dated November 13, 2007, or later Transport Canada approved revision.

Limitations and Conditions:

1. Maintenance must be in accordance with Bombardier Aerospace Mandatory Maintenance Manual Supplement G-TM05104506, Revision A, Transport Canada approved on February 1, 2008, or later Transport Canada approved revision.
2. The installer must determine whether this design change is compatible with previously approved modifications.
3. If the holder agrees to permit another person to use the certificate to alter a product, the holder must give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: January 22, 2008

Date reissued:

Date of issuance: April 28, 2008

Date amended:



By direction of the Administrator

(Signature)

Anthony Socias
Manager
New York Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.