

Supplemental Type Certificate

IMPORT

Number ST02437NY

This certificate issued to Scandinavian Avionics Design GmbH
Rothenbaumchaussee 135
20149 Hamburg
Germany

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.

Original Product -- Type Certificate Number: A33EU
Make: Dassault-Aviation
Model: Falcon 10

Description of Type Design Change:

Installation of Kannad 406 Emergency Locator Transmitter in accordance with Engineering Order Document 2022256-EO-03, Issue 1 or later approved EASA revision.

Limitations and Conditions :

1. EASA accepted Aircraft Maintenance Manual Supplement, Document No. 2022256-CA-03, Issue 1, dated June 06, 2007 is required for this installation.
2. EASA approved Airplane Flight Manual Supplement, 406 ELT, Document No. 2022256-AM-03, Issue 2, dated April 2005 is required for this installation.
3. If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission.
4. The Installer must determine whether this design change is compatible with previously approved modifications.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: May 09, 2007

Date reissued:

Date of issuance: July 30, 2007

Date amended:

By direction of the Administrator



(Signature)

Anthony Socias
Manager
New York Aircraft Certification Office

(Title)