

United States of America
Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate

IMPORT

Number **SR02792NY**

This certificate issued to Mecaer Aviation Group S.p.A
Via dell' Artigianato, 1
63033 Montepandone (AP) Italy

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 29 of the Federal Aviation Regulations.

Original Product Type Certificate Number: R00002RD

Make: Agusta S.p.A

Model: AB139, AW139

Description of Type Design Change:

Installation of New Liners VIP Silens P/N 6AB1AD010-001 per Owner's Manual P/N 6AB1WNM-2-17, Rev C, dated June 29, 2009. The following items are required with this installation: The Instructions for Continued Airworthiness (ICA), Owner's Manual (Installation Manual, Maintenance Manual and Illustrated Parts Breakdown) No. 6AB1WNM-2-17, Rev C, dated June 29, 2009, and EASA approved Rotorcraft Flight Manual Supplement No. 6AB1RFM 1-9, Rev A, dated May 15, 2009, or later EASA approved revision.

Limitations and Conditions:

1. Hinged Passengers Doors Kit P/N 4G5212F00111 is a prerequisite for this installation.
2. The installer must determine whether this design change is compatible with previously approved modifications.
3. If the holder agrees to permit another person to use the certificate to alter a product, the holder must give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: November 10, 2009

Date reissued: January 31, 2014

Date of issuance: March 29, 2010

Date amended:



By direction of the Administrator

(Signature)

Gaetano Sciortino
Manager
New York Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.