

United States of America
Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate

Number SR02415AK

This certificate issued to Vector Aerospace Helicopters Services USA, Inc.
1873 Shell Simmons Dr., Suite 110
Juneau, Alaska 99801

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 29 of the Federal Aviation Regulations

Original Product – Type Certificate Number: H4EU
Make: EUROCOPTER FRANCE
Model: AS332C, AS332L, AS332L1

Description of Type Design Change:

Installation of cockpit voice and data recorder system in accordance with Vector Aerospace Helicopter Services USA, Inc., Master Drawing List, HP 332-23-71-102, Revision F, dated April 23, 2014, or later FAA approved revision.

Limitations and Conditions:

1. The compatibility of this design change with previously approved modifications must be determined by the installer.
2. If the holder agrees to permit another person to use this Certificate to alter the product, the holder shall give the other person written evidence of that permission.
3. For Instruction for Continued Airworthiness, refer to Vector Aerospace Helicopter Services USA, Inc., Document No. HP 332-23-71-251, Revision E, dated May 23, 2014, or later FAA approved revision.
4. FAA approved Flight Manual Supplement, Document FMS HP 332-23-71-301, Revision A, dated July 24, 2014, or later FAA approved revision is a required part of this installation.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: July 11, 2012

Date reissued:

Date of issuance: July 10, 2013

Date amended: July 25, 2014



By direction of the Administrator

(Signature)

August A. Asay
Manager, Anchorage Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.