

United States of America
Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate

IMPORT

Number ST02554NY

This certificate issued to Bombardier Aerospace Inc.
200 Chemin Cote Vertu Road West
Dorval, Quebec
Canada H4S 2A3

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.

Original Product -- Type Certificate Number: T00003NY
Make: Bombardier
Model: BD-700-1A10, BD-700-1A11

Description of Type Design Change:

Installation, Interior Completion In Service Improvement Modifications. Modifications to be completed in accordance with ACS-NAI Ltd. Modification Data Summary F727000, Revision F, approved September 14, 2010 or later Transport Canada approved revisions.

Limitations and Conditions:

1. Installation of one of the following STCs is a prerequisite:

SA8164NM-D	ST01096NY	ST00996NY	ST02033NY	ST01806NY	SA8187NM-D	ST01995AT	ST01165NY
ST02254AT	ST01232NY	ST01371NY	ST01357NY	ST01293NY	ST01137LA	ST02365AT	ST01345NY
ST02140NY	ST00604SE-D	ST01376NY	ST01199LA	ST01402NY	ST01438NY	ST01310LA	ST01417NY
ST02556AT	ST01238LA	ST01418NY	ST00621SE-D	ST01622NY	ST01427NY	ST01444NY	ST01350LA
ST01494NY	ST01619NY	ST01870NY	ST01688NY	ST01527NY	ST01554NY	ST01578NY	ST01579NY
ST01574NY	ST01575NY	ST01678NY	ST01633NY	ST02001NY	ST018181NY	ST01706NY	ST01665NY
ST01685NY	ST01741NY	ST01815NY	ST01833NY	ST02002NY	ST01844NY	ST01904NY	ST01953NY
ST01917NY	ST02194NY	ST02049AT	ST01171NY	ST01186NY	ST01936NY	ST02177NY	ST02095AT
ST01240NY	ST01227NY	ST02255AT	ST06033SE-D	ST01382NY	ST01415NY	ST01155LA	ST01338NY
ST01341LA	ST02332AT	ST02356AT	ST01284LA	ST01339LA	ST01325LA		

(See Continuation Sheet 2)

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: July 8, 2008

Date reissued:

Date of issuance: August 4, 2008

Date amended: February 3, 2011

By direction of the Administrator



(Signature)

Anthony Socias
Manager
New York Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

United States of America
Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate
(Continuation Sheet)

Number ST02554NY

Date of Amendment: February 3, 2011

Limitations and Conditions (Continued).

2. For Instructions for Continued Airworthiness refer to:
 - Aero Consulting Services Ltd. Installation, Alternate Cockpit Phone with Backlight G302071-ICA Revision NC dated June 15, 2009 or later Transport Canada accepted revision
 - Aero Consulting Services Ltd. Installation, Door Handle Modification G391071-ICA Revision NC dated September 08, 2009 or later Transport Canada accepted revision.
 - Bombardier Installation of an Access Panel for the Chiller Filter BAS67058003-ICA Revision NC dated March 26, 2010 or later Transport Canada accepted revision.
 - Bombardier Quick Potable Water Treatment Unit Quick Disconnects BAS67039013-ICA Revision A dated May 19, 2010 or later Transport Canada accepted revision.
3. The Installer must determine whether this design change is compatible with previously approved modifications.
4. If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission.

---END---