

United States Of America
Department of Transportation - Federal Aviation Administration
Supplemental Type Certificate

Number SE00946LA

This Certificate issued to HOLLOWAY ENGINEERING CO.
262 SPANISH CREEK ROAD
QUINCY, CALIFORNIA 95971

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 33 of the Federal Aviation Regulations.

Original Product Type Certificate Number : E-162-12

Make : Continental

Model : W670-6A, W670-6N

Description of Type Design Change: Installation of engine crankshaft front and rear bearings per drawings and instruction information contained in Holloway Engineering Co. Bearing Changes on Continental W-670 Manual Report No. 9000, Rev. A dated March 9, 2000, or later FAA approved revisions.

Limitations and Conditions: The approval of the change in type design applies to the basic engine of the specified models that are otherwise unmodified. This approval should not be extended to other specific engines of the models on which other previously approved modifications are incorporated, unless it is determined that the interrelationship between this installation and any previously approved configuration will not introduce any adverse effect upon the airworthiness of that engine. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : February 22, 1999

Date reissued :

Date of issuance : April 20, 2000

Date amended :



By direction of the Administrator

[Signature]
(Signature)

Manager, Propulsion Branch
Los Angeles Aircraft Certification Office
(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

