

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number SA1953NM

This certificate issued to Telair US LLC
500 Gateway Drive
Goldsboro, NC 27534

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.

Original Product -- Type Certificate Number : A16WE
Make : Boeing
Model : 737-210C, 737-2A9C

Description of Type Design Change:

Installation of Brownline Cargo Pallet Restraint System P/N 48325-101 in accordance with FAA sealed Brownline Loading Arrangement Drawing 48412, Revision N/C, dated November 11, 1982, or later FAA approved revision.

Limitations and Conditions:

- 1) The installer must determine whether this design change is compatible with previously approved modifications.
- 2) If the holder agrees to permit another person to use this certificate to alter the product, the holder must give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : November 23, 1982

Date reissued : November 25, 1986; March 26, 2015

Date of issuance : March 31, 1983

Date amended : January 13, 1984



By direction of the Administrator

Original Signed By:
Karol Mordasiewicz

(Signature)

Karol Mordasiewicz
Manager, Airframe & Administrative Branch
Chicago Aircraft Certification Office

(Title)

United States of America
Department of Transportation - Federal Aviation Administration
Supplemental Type Certificate
(Continuation Sheet)

Number

United States of America
Department of Transportation - Federal Aviation Administration
Supplemental Type Certificate
(Continuation Sheet)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.