

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number SE00327AT

This certificate issued to

Bell Helicopter Textron, Inc.
441 Industrial Park Road
Piney Flats, TN 37686

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 33 of the Federal Aviation Regulations.

Original Product -- Type Certificate Number: E10CE
Make: Rolls-Royce Corporation
Model: 250-B17, -B17B, -B17C, -B17D, -B17E, -B17F,
-B17F-1, -B17F-2

Description of Type Design Change:

Installation of Pc Safety Valve Kit in accordance with Report No. AA-92005, "Installation Instructions, Pc Safety Valve Kit on Allison 250-C20 and -B17 Series Engines", Rev. H, dated 4/8/93, or later FAA Approved revision.

Limitations and Conditions:

The installer must determine whether this design change is compatible with previously approved modifications. If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: October 12, 1992

Date reissued: May 29, 2013

Date of issuance: September 07, 1993

Date amended: November 17, 1997;
August 03, 1999



By direction of the Administrator

(Signature)
Scott A. Horn, Acting Manager,
Rotorcraft Certification Office,
Southwest Region

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate
(Continuation Sheet)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.