

United States of America  
Department of Transportation -- Federal Aviation Administration  
**Supplemental Type Certificate**

*Number* SA5-33

*This certificate issued to*

Wilbur Repair Service  
In care of Marguerite Benson and Anne Wilbur  
PO Box 770744, 21446 Eagle River Road  
Eagle River, AK 99577

*certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 3 and 4a of the Civil Air Regulations*

*Original Product - Type Certificate Number:* 691, 725, 780, 797  
*Make:* Piper  
*Model:* PA-11, PA-12, J3C, J5C, J5A, and PA-14

*Description of Type Design Change:*

Removed unbalanced tail surfaces and installed balanced tail surfaces. Install elevators, Piper P/N 12789-00 and 12789-01 and stabilizers, Piper P/N 12790-00 and 12790-01 per Wilbur Repair Service Instruction Sheet Number 1, dated May 18, 1961.

*Limitations and Conditions:*

Compatibility of this design change with previously approved modifications must be determined by the installer.

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application:* May 18, 1961

*Date reissued:* June 12, 1997; July 8, 2016

*Date of issuance:* May 18, 1961

*Date amended:*



*By direction of the Administrator*

(Signature)

August A. Asay  
Manager, Anchorage Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.