

Supplemental Type Certificate

IMPORT

Number ST02505NY

This certificate issued to DECA Aviation Engineering Limited
200-7050 Telford Way
Mississauga, Ontario
Canada L5S 1V7

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.

Original Product Type Certificate Number: T00003NY

Make: Bombardier Inc.

Model: BD-700-1A10

Description of Type Design Change:

Interior modification in accordance with DECA Aviation Modification Summary MS07158 Revision 1, dated September 18, 2007 or later Transport Canada approved revisions.

Limitations and Conditions:

1. FAA STC ST01338NY (Transport Canada LSTC O-LSA01-007) must be installed as a prerequisite or concurrently with this modification.
2. FAA STC ST02504NY (Transport Canada LSTC O-LSA07-261/D) must be installed as a prerequisite or concurrently with this modification.
3. Maintenance is to be in accordance with Instructions for Continued Airworthiness ICA07158 Revision 1, dated November 13, 2007 or later Transport Canada accepted revisions.
4. Operations are to be in accordance with Flight Manual Supplement FMS07158 Revision 1, dated December 21, 2007 or later Transport Canada approved revisions.
5. Divans may not be occupied during Taxi, Take-off and Landing.
6. You can not use descriptive data about this design change to duplicate other products. This approval is limited to only the installation made in Bombardier Inc. BD-700-1A10, Serial Number 9004. This STC does not permit manufacturing of parts for multiple installations.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: December 31, 2007

Date reissued:

Date of issuance: January 30, 2008

Date amended:



By direction of the Administrator

(Signature)

Anthony Socias
Manager
New York Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.