

United States of America  
Department of Transportation -- Federal Aviation Administration

# Supplemental Type Certificate

*Number* SA2404SW

*This certificate issued to*

ACC-KP, LLC  
4554 Claire Chennault St.  
Addison, TX 75001

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 10/4b of the Civil Air Regulations.*

*Original Product -- Type Certificate Number:* A7EU

*Make:* Avions Marcel Dassault

*Model:* Fan Jet Falcon, Fan Jet Falcon Series D, E, F

*Description of Type Design Change:*

Installation of a system to disable the take off out of trim warning system when high power is applied during operation of the thrust reversers after landing according to Drawing No. DK3 dated 1/12/77, and Installation Instructions DK4 dated 1/12/77, or later FAA approved revision.

*Limitations and Conditions:*

1. Fan Jet Falcon - with Service Bulletin AMD No. 179, Flight Controls - Tailplane Actuator with increased travel and position indication.
2. Thrust Reversers must be installed in accordance with STC SA2568WE.

If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission.

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application:* January 20, 1977

*Date reissued:* 3/22/90; 8/14/92;  
9/14/10; 5/17/13

*Date of issuance:* February 8, 1977

*Date amended:*



*By direction of the Administrator*

\_\_\_\_\_  
(Signature)  
S. Frances Cox, Manager,  
Special Certification Office,  
Southwest Region

\_\_\_\_\_  
(Title)

United States of America  
Department of Transportation -- Federal Aviation Administration  
**Supplemental Type Certificate**  
(Continuation Sheet)

---

*Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.*