

United States Of America
Department of Transportation - Federal Aviation Administration
Supplemental Type Certificate

Number SR01924LA

This Certificate issued to Integrated Flight Systems
3900 Falcon Way West, Hangar 16S
Fort Worth, Texas 76106

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part *27 of the Civil Air or Federal Aviation Regulations.*

*Certification basis is set forth in Type Certificate Data Sheet H3WE

Original Product Type Certificate Number: H3WE

Make: MD Helicopters Inc.

Model: 369, 369A, 369H, 369HM, 369HS, 369HE, 369D, 369E, 369F, 369FF, 500N, 600N

Description of Type Design Change: Installation of a Platinum Aviation cockpit pedestal slant panel in accordance with Platinum Aviation Master Drawing List 510409MDL, Revision IR, dated July 4, 2005, or later FAA approved revisions.

Limitations and Conditions: The installer must determine whether this design change is compatible with previously approved modifications. The FAA has not certified the equipment for which these provisions are intended. You must get additional FAA approval to install this equipment. The FAA must evaluate the installation to ensure it complies with the applicable airworthiness standards. If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: February 7, 2004

Date reissued: May 28, 2009

Date of issuance: October 23, 2006

Date amended:



By direction of the Administrator

(Signature)
Manager, Airframe Branch
Los Angeles Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.