

Supplemental Type Certificate

Number SA01184SE

This certificate, issued to Pacific AeroSport, LLC
17705 49th Place NE
Arlington, WA 98223

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 23 of the Federal Aviation Regulations.

Original Product—Type Certificate Number: A46CE
Make: Symphony Aircraft Industries Inc.
Model: OMF-100-160, SA-160

Description of the Type Design Change: Installation of a Sensenich Propeller Model 74DM6S11-1-56 per Pacific AeroSport, LLC Document PAS-02, Revision A dated October 26, 2005 or later FAA approved revision.

Limitations and Conditions: Approval of this change in type design applies to the above model aircraft only. This approval should not be extended to other aircraft of these models on which other previously approved modifications are incorporated unless it is determined that the relationship between this change and any of those other previously approved modifications, including changes in type design, will introduce no adverse effect upon the airworthiness of that aircraft. A copy of this Certificate and the Pilot Operating Handbook Supplement, dated December 8, 2005 or later FAA approved revision, must be maintained as part of the permanent records for the modified aircraft.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: June 25, 2002

Date reissued:

Date of issuance: March 4, 2003

Date amended: October 6, 2003, December 8, 2005



By direction of the Administrator

(Signature)
Acting Manager, Seattle Aircraft
Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.