

United States of America  
Department of Transportation -- Federal Aviation Administration  
**Supplemental Type Certificate**  
**IMPORT**

*Number* **SR02180NY**

*This certificate issued to*

Heli-Lynx Helicopter Services, Inc.  
Stoney Creek Airport  
684 Mud Street East, Hangar 1  
Stoney Creek, ON, Canada, CN L8J 3C9

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 27 of the Federal Aviation Regulations.*

*Original Product -- Type Certificate Number:*

H11EU

*Make:*

Eurocopter France

*Model:*

AS355E, AS355F, AS355F1, AS355F2

*Description of Type Design Change:* Installation of airframe-mounted engine oil filter assembly.

*Limitations and Conditions:*

1. Installation must be in accordance with Heli Lynx Helicopter Service Installation Manual Report No. IM-PA-04-011-91-01, Issue 1, Rev. Original, Transport Canada approved February 23, 2005 or later Transport Canada approved revisions.
2. Operation must be in accordance with Heli Lynx Helicopter Service Flight Manual Supplement No. FMS-PA-04-011-91-01, Issue 1, Rev. Original, Transport Canada approved April 5, 2005 or later Transport Canada approved revisions.

(See Continuation Sheet 2)

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application:* May 26, 2005

*Date reissued:*

*Date of issuance:* November 29, 2005

*Date amended:*



*By direction of the Administrator*

(Signature)

Anthony Socias  
Manager  
New York Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

United States of America  
Department of Transportation -- Federal Aviation Administration

# Supplemental Type Certificate

(Continuation Sheet)

*Number* SR02180NY

*Limitations and Conditions* (Continued):

3. Maintenance must be in accordance with Heli Lynx Helicopter Service Maintenance Manual Supplement Report No. ICA-PA-04-011-91-05-01, Issue 1, Rev. Original, Transport Canada accepted April 5, 2005 or later Transport Canada accepted revisions.
4. Compatibility of this design change with previously approved modifications must be determined by the installer.
5. If the holder agrees to permit another person to use the certificate to alter the product, the holder shall give the other person written evidence of that permission.

...END...