

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number SR09488RC

P/N: ST2885RC-R
PM JK
ASW-170

This certificate issued to

Helifab, Inc.
1318 Smede Hwy
Broussard, LA 70518

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 29 of the Federal Aviation Regulations.

Original Product -- Type Certificate Number: H4SW
Make: Bell Helicopter Textron
Model: 212, 412, 412EP

Description of Type Design Change: Installation of Tail Boom Baggage Door Actuator in accordance with Helifab, Inc. Master Drawing and Document List No. HF-412-DL-100, Revision A, dated July 2, 2007, or later FAA approved revisions. Instructions for Continued Airworthiness, Helifab, Inc. Report Number HF-412-ICA-Baggage Door Actuator-01, Revision IR, dated September 5, 2006, or later FAA accepted revisions are required for this installation.

Limitations and Conditions: The installer must determine whether this design change is compatible with previously approved modifications. If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: September 05, 2006

Date reissued:

Date of issuance: August 03, 2007

Date amended:



By direction of the Administrator

(Signature)
Lance T. Gant, Manager
Rotorcraft Certification Office
Southwest Region

(Title)

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate
(Continuation Sheet)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.