

United States of America
Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate

IMPORT

Number ST02513NY

This certificate issued to Dassault Falcon Service
B.P. 10,
Aeroport du Bourget
93352 Le Bourget cedex
France

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.

Original Product -- Type Certificate Number: A50NM

Make: Dassault Aviation

Model: Falcon 2000, Falcon 2000EX

Description of Type Design Change:

Incorporation of Runway Awareness and Advisory System (RAAS) function EGPWS Honeywell Mk V in accordance with Master Document List DFS-DE-17-FD-D100 Issue A1 dated November 20, 2007.

Limitations and Conditions:

1. EASA accepted Aircraft Maintenance Manual Supplement, Document No. SMM 31-95-11 A1, dated April 8, 2008.
2. EASA approved Airplane Flight Manual Supplement, DFS-F2000-005, Revision IR, dated November 20, 2007.
3. If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission.
4. The Installer must determine whether this design change is compatible with previously approved modifications.
5. This STC is applicable only on Falcon 20000 and Falcon 2000EX equipped with:
 - Honeywell EGPWS Mk V software 212-212 or later with terrain display in EFIS
 - Proline IV Avionics Suite V6 with two Collins GPS 4000 series
 - EGPWS lighted switches on the pilot's primary field of view
 - Terrain database 435 or later is required

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: January 10, 2008

Date reissued:

Date of issuance: April 28, 2008

Date amended:



By direction of the Administrator

(Signature)

Anthony Socias
Manager
New York Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.