

United States of America  
Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate  
IMPORT

Number SR02486NY

*This certificate issued to* Heli-Lynx Helicopter Services, Inc.  
Stoney Creek Airport  
684 Mud Street E, Hangar 1  
Stoney Creek, Ontario, Canada L8J 3C9

*certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 27 of the Federal Aviation Regulations.*

*Original Product -- Type Certificate Number:* H9EU  
*Make:* Eurocopter France  
*Model:* AS350B, BA, B1, B2, D, D1

*Description of Type Design Change:*

Installation of ADC engine scavenge oil filter with internal full flow chip detector in engine lubrication scavenge circuit on AS350 series helicopters with LTS101 engines installed. Installation is in accordance with Heli-Lynx Helicopter Services Installation Manual IM-PA-06-039-91-01, Issue 2, Revision Original, Transport Canada Approved June 14, 2007 and Heli-Lynx Helicopter Services Master Drawing List MDL-PA-06-039-91-01, Issue 2, Revision Original, Transport Canada approved June 14, 2007, or later Transport Canada approved revisions.

*Limitations and Conditions:*

1. Installation is in accordance with Heli-Lynx Helicopter Services Installation Manual IM-PA-06-039-91-01, Issue 2, Revision Original, Transport Canada Approved June 14, 2007 and Heli-Lynx Helicopter Services Master Drawing List MDL-PA-06-039-91-01, Issue 2, Revision Original, Transport Canada approved June 14, 2007, or later Transport Canada approved revisions.

(See Continuation Sheet 2)

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application:* June 17, 2007

*Date reissued:*

*Date of issuance:* November 30, 2007

*Date amended:*



*By direction of the  
Administrator* \_\_\_\_\_

(Signature)

Anthony Socias  
Manager  
New York Aircraft Certification Office

(Title)

United States of America  
Department of Transportation -- Federal Aviation Administration  
**Supplemental Type Certificate**  
(Continuation Sheet)

*Number* **SR02486NY**

Date of Issuance: November 30, 2007

*Limitations and Conditions* (Continued).

2. Prerequisite requirements:  
The rotorcraft must be equipped with the Honeywell LTS101 engine in accordance with:  
For AS350BA: FAA STC SR02295NY, or FAA STC SH5815SW, or FAA STC SR00805SE.  
For AS350B: FAA STC SH5815SW.  
For AS350B2: FAA STC SR02295NY, or FAA STC SR01647SE.  
For AS350D: FAA STC SH5815SW, or FAA STC SR00772SE.  
For AS350D1: TCDS H9EU
3. Operation is in accordance with Heli-Lynx Helicopter Services Flight Manual Supplement FMS-PA-06-039-91-01, Issue 1, Revision A, Transport Canada approved June 14, 2007, or later Transport Canada approved revisions.
4. Maintenance is in accordance with Heli-Lynx Helicopter Services Instructions for Continued Airworthiness ICA-PA-06-039-05-01, Issue 2, Revision A, dated June 14, 2007, FAA accepted November 29, 2007 or later Transport Canada accepted revisions.
5. The installer must determine whether this design change is compatible with previously approved modifications.
6. If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission.

---- END ----