

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate
IMPORT

Number ST02167NY

This certificate issued to MTI-Polyfab Inc.
7391 Pacific Circle
Mississauga, Ontario
L5T 2A4 Canada

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.

Original Product -- Type Certificate Number: T00003NY
Make: Bombardier Inc.
Model: BD-700-1A11, BD-700-1A10

Description of Type Design Change:

Installation of Insulation Blankets for BD-700-1A11, BD-700-1A10 aircraft models to be done in accordance with Magnifoam Technology Inc. Modification Summary MS03052005, Issue NC, dated May 3, 2005 and Modification Summary MS01010607 Issue NC, dated January 6, 2007 respectively, or later Transport Canada approved revision.

Limitations and Conditions:

1. Maintenance for the BD-700-1A11 and the BD-700-1A10 aircraft models to be done in accordance with Magnifoam Technology Inc. Aircraft Maintenance Manual Supplements MMS-MGL-05-05, Revision NC, dated May 3, 2005 and Aircraft Maintenance Manual Supplements forms MMS-BGX-07-04, Revision A, dated January 6, 2007 respectively, or later Transport Canada accepted revision.
2. The installer must determine whether this design change is compatible with previously approved modifications.
3. If the holder agrees to permit another person to use the certificate to alter a product, the holder must give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: September 28, 2005

Date reissued: October 27, 2005

Date of issuance: October 24, 2005

Date amended: June 22, 2007



By direction of the Administrator

(Signature)

Anthony Socias
Manager
New York Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.