

United States of America
Department of Transportation Federal Aviation Administration
Supplemental Type Certificate

Number SR00275DE-D

This certificate, issued to

**Air Methods Corporation
7301 South Peoria
Englewood, Colorado 80112**

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 27 of the Federal Aviation Regulations.

Original Product—Type Certificate Number: H2SW
Make: Bell Helicopter Textron
Model: 407

Description of the Type Design Change:

Installation of Emergency Medical Interior System in accordance with Air Methods Corporation Configuration Control Drawing No. 189-9000, Revision (-), dated January 7, 1996, or later FAA approved revision.

Limitations and Conditions:

1. This approval should not be extended to rotorcraft of this model on which other previously approved modifications are incorporated unless it is determined that the interrelationship between this change and any of those other previously approved modifications, including changes in type design, will introduce no adverse effect upon the airworthiness of that rotorcraft.
2. Instructions for Continued Airworthiness Document No. AMMS 050-0219, Rev. (A), dated 4/9/97, or later FAA accepted revision is a required part of the permanent records for the modified aircraft, and defines the inspection and maintenance requirements.
3. A copy of this Certificate and FAA approved Rotorcraft Flight Manual Supplement RFMS 080-0219, Rev. (-), dated 4/16/97, or later FAA approved revision must be maintained as part of the permanent records for the modified rotorcraft.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: June 18, 1996

Date reissued: June 21, 2006

Date of issuance: April 16, 1997

Date amended:



By direction of the Administrator

Robert C. Lazaroff (*Signature*), DAS administrator
DAS-635841-NM
Air Methods Corporation

(*Title*)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.