

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate
IMPORT

Number **SR02056NY**

This certificate issued to

Aero-Dyne Repair Services, Ltd.
PO Box 3966
Olds, Alberta
Canada T4H 1P7

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 27 of the Federal Aviation Regulations.

Original Product -- Type Certificate Number: H2SW
Make: BELL
Model: 206B, 206L, 206L-1, 206L-3, 206L-4

Description of Type Design Change:

Installation of Helicopter Performance Monitoring System is to be done in accordance with Aero-Dyne Repair Services Engineering Order (EO) EO332101, Revision 1, dated July 25, 2003, or later Transport Canada approved revision. Audio option is to be installed in accordance with Aero-Dyne Repair Services Engineering Order (EO) EO332102, dated April 2, 2003, or later Transport Canada approved revisions.

Limitations and Conditions:

1. Aero-Dyne Repair Services Rotorcraft Flight Manual Supplement No. FMS332101, Revision 1, dated July 24, 2003, or later Transport Canada approved revision, is required with this modification.
2. Maintenance Manual Supplement MMS332101, Revision 1, dated April 2, 2003, or later Transport Canada accepted revision, is required as Instructions for Continued Airworthiness with this modification.
3. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.
4. Compatibility of this design change with previously approved modifications must be determined by the installer.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: July 14, 2004

Date reissued:

Date of issuance: February 09, 2005

Date amended:



By direction of the Administrator

(Signature)

Vito A. Pulera
Manager
New York Aircraft Certification Office

(Title)