

United States Of America  
Department of Transportation - Federal Aviation Administration  
**Supplemental Type Certificate**

*Number* SR02535LA

*This Certificate issued to* Diagnostic Solution International LLC  
2580 East Philadelphia Street, Unit C  
Ontario, CA 91761

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 29 of the Federal Aviation Regulations.*

*Original Product Type Certificate Number:* H13EU  
*Make:* Airbus Helicopters Deutschland GmbH  
*Model:* MBB-BK 117 C-1 and MBB-BK 117 C-2

*Description of Type Design Change:* Installation of Honeywell Model 15175 VXP Health Monitoring System on Airbus Helicopters Deutschland, Model MBB-BK 117 C-1 and MBB-BK 117 C-2 in accordance with FAA Approved Master Drawing List, Document Number 25698, Revision "NC" dated March 20, 2015, or later FAA Approved Revisions.

*Limitations and Conditions:* The installation should not be incorporated in any aircraft unless it is determined that the interrelationship between this installation and any previously approved configuration will not introduce any adverse effect upon the airworthiness of the aircraft. The approval of this modification applies to the above noted aircraft model series only. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application:* December 23, 2013

*Date reissued:*

*Date of issuance:* May 28, 2015

*Date amended:*



*By direction of the Administrator*

\_\_\_\_\_  
(Signature)  
Manager, System & Equipment Branch  
Los Angeles Aircraft Certification Office

\_\_\_\_\_  
(Title)

*Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.*

INSTRUCTIONS: The transfer endorsement below may be used to notify the appropriate FAA Regional Office of the transfer of this Supplemental type certificate.

The FAA will reissue the certificate in the name of the transferee and forward it to him.

\_\_\_\_\_

**TRANSFER ENDORSEMENT**

Transfer the ownership of the Supplemental Type Certificate Number \_\_\_\_\_

to *(Name of transferee)* \_\_\_\_\_

*(Address of transfer)* \_\_\_\_\_

*(Number and street)*

\_\_\_\_\_  
*(City, State, and Zip code)*

from *(Name of grantor) (Print or type)* \_\_\_\_\_

*(Address of grantor)* \_\_\_\_\_

*(Number and street)*

\_\_\_\_\_  
*(City, State, and Zip code)*

Extent of Authority (if licensing agreement): \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Date of Transfer: \_\_\_\_\_

Signature of grantor *(In ink)*: \_\_\_\_\_

\_\_\_\_\_  
*Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.*