

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number SA683WE

This certificate issued to RAYJAY Parts LLC
10 Harbor Island Drive
Key Largo, Florida 33037

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 3 of the Civil Air Regulations.

Original Product-Type Certificate Number: 6A1
Make: Aero Commander
Model: 500A

Description of Type Design Change: Installation of turbocharged Continental IO-470-M engines in accordance with FAA Sealed Roto- Master (Rajay) Drawing List No. RJ2050 or later FAA approved revision.

Limitations and Conditions: The engines must be previously modified to incorporate turbochargers in accordance with Supplement Type Certificate No. SE96SO. The approval of this change in type design applies to the basic Aero Commander Model 500A aircraft only. This approval should not be extended to other aircraft of the same model on which other modifications have been made unless it has first been determined that the interrelationship between these various modifications will have no adverse effect on the airworthiness of the aircraft. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission. FAA Approved Roto-Master (Rajay) Airplane Flight Manual Supplement dated May 6, 1964 or later FAA approved revision is required with this installation.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: January 27, 1964

Date of issuance: May 6, 1964

Date reissued: Jan. 14, 1969; Feb. 10, 1982;
Oct. 30, 1987; Sept. 22, 1995;
Dec. 12, 2003; July 3, 2006

Date amended: Mar. 21, 1985



By direction of the Administrator

(Signature)
Melvin D. Taylor, Manager
Atlanta Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

