

United States of America
Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate

Number SA257CE

This certificate issued to RAYJAY Parts LLC
10 Harbor Island Drive
Key Largo, Florida 33037

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 3 of the Civil Air Regulations.

Original Product-Type Certificate Number : 6A1
Make : Aero Commander (Rockwell International)
Model : 500

Description of Type Design Change: Installation of turbocharged Lycoming engines, model IO-540-A1A5 with Hartzell HC-A3VK-2/V7636D propellers in accordance with Riley Aeronautics, Inc. Bulletin 64-5. Riley Aeronautics, Inc. AFM Supplement dated July 27, 1964 required.

Limitations and Conditions: This approval should not be extended to other specific airplanes of this model on which other previously approved modifications are incorporated unless it is determined that the interrelationship between this change and any of those other previously approved modifications will introduce no adverse effects on the airworthiness of the airplane. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

A.D. 65-02-03 (Rajay) applicable to this installation.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : May 1, 1964

Date of issuance : July 27, 1964

Date reissued : Aug. 1, 1974; Dec. 5, 1974; Feb. 10, 1982;
Oct. 30, 1987; Sept. 22, 1995; Apr. 1, 2004;
Apr. 26, 2005; July 3, 2006

Date amended :

By direction of the Administrator



(Signature)

Melvin D. Taylor, Manager
Atlanta Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

