

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number SA404CE

This certificate issued to

BF Goodrich Aerospace
Lighting Systems Division
3445 South 5th Street
Phoenix, AZ 85040

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 3 of the Civil Air Regulations.

Original Product--Type Certificate Number:

6A1, 2A4

Make:

Aero Commander

Model:

500, 500A, 500B, 500U, 500S, 560, 560A, 560E, 560F,
680, 680F, 680FL, 680FL(P), 680T, 680W, 720

Description of Type Design Change: Installation of Hoskins Supplemental Position Light System which includes Model A Wing Tip Lights, and Model D or K (dual) Tail Light.

Data Required: (1) General installation instructions dated September 19, 1965. Hoskins Specification Sheets, pages 1 thru 4, Dated September 19, 1965. Hoskins drawings 30-0020, Sheets 1 & 2 and 30-0108 or Specifications Sheets P/N 65-0034, Dated February 21, 1968, P/N 65-0033-1, Dated March 15 or June 30, 1968.

Limitations and Conditions: **LIMITATION OF APPLICABILITY.** This approval should not be extended to other specific airplanes of these models on which other previously approved modifications are incorporated unless it is determined that the interrelationship between this change and any of those previously approved modifications will introduce no adverse effect upon the airworthiness of the airplane.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: July 19, 1965

Date reissued: May 4, 1970, April 1, 1990,
September 25, 1995, January 31, 1996,
September 30, 2011

Date of issuance: March 17, 1966

Date amended: September 9, 1968



By direction of the Administrator

(Signature)

Melvin D. Taylor
Manager, Atlanta Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.