

United States Of America
Department of Transportation - Federal Aviation Administration

Supplemental Type Certificate

This certificate has been reissued to replace the original certificate reported as lost.

Number SA3406WE

This Certificate issued to United Aeronautical Corporation
7360 Laurel Canyon Blvd.
North Hollywood, California 91605

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 4b of the Civil Air Regulations. Effective October 1, 1949 and amendment 4b-2 dated August 25, 1955.

Original Product Type Certificate Number: 6A3

Make: The Boeing Company

Model: R6D-1 Serial Number 43690 – One Only

Description of Type Design Change: Modification of the oxygen system including the addition of a supply bottle, pressure relief valve, and a microphone in the smoke masks in accordance with Aero Union Drawing List Number AU8100 dated April 22, 1977, or later sealed revision.

Limitations and Conditions: Data pertaining to this modification are considered inadequate for duplication in other aircraft. This approval is limited to the installation made in Douglas Model R6D-1 Serial Number 43690 only.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: April 22, 1977

Date reissued: April 15, 2015

Date of issuance: May 19, 1977

Date amended:



By direction of the Administrator

(Signature)

Supervisor, Technical and Administrative
Support Staff
Los Angeles Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

United States Of America
Department of Transportation - Federal Aviation Administration
Supplemental Type Certificate
(Continuation Sheet)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.
