

United States of America  
Department of Transportation -- Federal Aviation Administration  
**Supplemental Type Certificate**

*Number* ST02389CH

*This certificate issued to* AAR Aircraft Services  
2825 W. Perimeter Road  
Indianapolis IN, 46241

*certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.* (See Type Certificate Data Sheet T00001SE for complete certification basis)

*Original Product--Type Certificate Number :* T00001SE

*Make :* Boeing

*Model :* 777-232

*Description of Type Design Change:*

Installation of a Centerline Partition and Bin Close-off, removal of existing M4 Galley and Flight Attendant Seat aft of the L1 doorway according to Master Drawing List, ERP 06-018, Revision IR, dated March 05, 2007, or later FAA approved revision.

*Limitations and Conditions :*

- 1) Compatibility of this design change with previously approved modifications must be determined by the installer.
- 2) A copy of this certificate or later FAA approved revision must be maintained as part of the permanent records for the modified aircraft.
- 3) If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission.
- 4) TIMCO STC ST0231AT-D, dated February 01, 2002 is previously installed.

*This certificate and the supporting data, which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application :* November 16, 2007

*Date reissued :*

*Date of issuance :* March 07, 2007

*Date amended :*

*By direction of the Administrator*



(Signature)

Mary Ellen A. Schutt  
Manager, Airframe and Administrative Branch  
Chicago Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.