

Book

Department of Transportation—Federal Aviation Administration

Supplemental Type Certificate

Number SA00655SE

This certificate, issued to: **Harley L. Howell, Jr.**
390 Dominion View Road
Colville, WA 99114

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 4a the Civil Air Regulations.

Original Product—Type Certificate Number A-766
Make: Globe (Swift)
Model: GC-1B

Description of the Type Design Change: Installation of a redesigned fiberglass engine cowl nose bowl, cowl and engine baffle modifications and a Cessna Spinner assembly (P/N 0752637-K-200) in accordance with Streamline Cowling Modification for GC-1B previously modified with Continental 210 H.P. Engine per STC SA53NW, Report #1, Revision A, dated September 1, 1998.

Limitations and Conditions: Data pertaining to this modification are considered inadequate for duplication in other aircraft. This approval is limited to the installation in Globe Model GC-1B aircraft, Serial Number 2056, Registration Number N78056 only. A copy of this Certificate shall be maintained as part of the permanent records for the modified aircraft.

Note: The above modification is applicable with the installation of the Continental IO-360-C engine and McCauley D2A34C67/76C-2 propeller per STC SA53NW.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.


This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: August 15, 1997
Date of issuance December 23, 1998

Date reissued:

Date amended:



By direction of the Administrator

 (Signature)
 Acting Manager, Seattle Aircraft
 Certification Office

 (Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.