

United States Of America
Department of Transportation - Federal Aviation Administration
Supplemental Type Certificate

Number SR09424RC

This Certificate issued to OuterLink Corporation
187 Ballardvale Street
Suite A260
Wilmington, MA 01887

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 27 of the Federal Aviation Regulations.

Original Product Type Certificate Number : H2SW
Make : Bell Helicopter Textron
Model : Bell 407

Description of Type Design Change:

Installation of an OuterLink Automatic Flight Following System and optional Electronic Flight Bag provisions in accordance with OuterLink Corporation Master Installation List NL462065004, Revision J, dated June 29, 2007, or later FAA-approved revision.

Limitations and Conditions:

1. OuterLink Corporation Rotorcraft Flight Manual Supplement NF462065002, Revision B, dated September 19, 2007, or later FAA-approved revision is required.
2. Instructions for Continued Airworthiness, OuterLink Corporation Document No. NM462065004, Revision C, dated February 14, 2007, or later FAA-accepted revision shall be made available to the operator at the time of installation.
3. Compatibility of this design with previously approved modifications must be determined by the installer.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the

Date of application : May 26, 2004

Date reissued : February 17, 2005; September 23, 2005;
August 5, 2011

Date of issuance : November 16, 2004

Date amended : November 2, 2006; September 19, 2007

Federal Aviation Administration.



By direction of the Administrator

(Signature)

Robert G. Mann
Manager
Boston Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.