

United States Of America
Department of Transportation - Federal Aviation Administration

Supplemental Type Certificate

Number SA00044LA

This Certificate issued to Dick Wilson – Aero Engineering
2413 Moreton Street
Torrance, California 90505

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 3 of the Civil Air Regulations. *(For Certification Basis, see Aircraft Specification No. 3A15)*

Original Product Type Certificate Number : 3A25

Make : Beech Aircraft Corporation

Model : 35-33, 35-A33, 35-B33, 35-C33, 35-C33A, E33, E33A, E33C, F33, F33A, F33C, G33, 36, A36, A36TC, B36TC

Description of Type Design Change: Installation of replacement Rudder Hinge Brackets in accordance with Master Drawing List DW-100, Rev. A, dated January 29, 1995; or later FAA approved revisions.

Limitations and Conditions: The approval of this Installation does not relieve any AD requirements. This installation should not be incorporated in any aircraft unless it is determined that the interrelationship between this change and any previously approved configuration will not introduce adverse effect upon the airworthiness of the aircraft. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : October 5, 1994

Date reissued : February 6, 2001

Date of issuance : March 09, 1995

Date amended :



By direction of the Administrator

Sharon L. Kennedy
(Signature)

Manager, Technical & Administrative Support
Staff, Los Angeles Aircraft Certification Office
(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.