

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number **SA00047DE**

This certificate, issued to: Straight Flight, Inc.
13251 E. Control Tower Rd, K-12
Englewood, CO 80112

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 3 of the Civil Air Regulations.

Original Product—Type Certificate Number: 6A1
Make: Twin Commander
Model: 500S (Serial Number 3083)

Description of the Type Design Change:

Installation of Copilot, left front passenger, and right front passenger bulb windows in accordance with Rocky Mountain Straight Flight Detail Drawing No. 173-001, Rev. N/C, dated August 4, 1993, and Installation Drawing No. 173-901, Rev. N/C, dated August 4, 1993, or later FAA approved revisions.

Limitations and Conditions:

1. Data pertaining to this modification are considered inadequate for duplication in other aircraft. This approval is limited to the installation in the Twin Commander Model 500S aircraft, Serial Number 3083 only.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration

Date of application: July 20, 1993

Date reissued: June 21, 2012

Date of issuance: August 9, 1993

Date amended:

By direction of the Administrator



(Signature)

Satish Lall
Northwest Mountain Regional Acting Manager
Denver Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.