

~~United States of America~~
Department of Transportation Federal Aviation Administration
Supplemental Type Certificate

Number SA4-504

This certificate issued to: Skyhaven, Inc.
25 Runway Road
Tunkhannock, PA 18657

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part * of the Civil Air Regulations.* *(Certification basis is set forth in Type Certification Data Sheet T.C. 685 and Bulletin 7A)

Original Product—Type Certificate Number: T.C. 685

Make: Stinson

Model: SR-10F

Description of the Type Design Change: Swing out type engine mount installation. Carburetor air heat installation. Oil tank fabrication and installation. Engine cowl installation. Oil cooler installation. Carburetor air scoop installation. Floyd M. Wardlow Drawing List Number 1.

Limitations and Conditions: This installation should not be incorporated in any aircraft unless it is determined that the interrelationship between this installation and any previously approved configuration will not introduce any adverse effect upon the airworthiness of the aircraft. The approval of this modification applies to the above noted airplane model series only. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission. A copy of this STC must be included in the permanent records of the modified aircraft.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: May 16, 1958

Date of issuance: May 27, 1958

Date reissued: September 2, 2003

Date amended: June 8, 2006



By direction of the Administrator

(Signature)
Acting Manager, Seattle Aircraft
Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.