

**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES**

LARGE AIRCRAFT

BIWEEKLY 2020-10

4/27/2020 - 5/10/2020



Federal Aviation Administration
Continued Operational Safety Policy Section, AIR-141
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806
Facsimile: (202) 512-2250

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects			
Biweekly 2020-01			
2019-23-04		The Boeing Company	727, 727-100, 727C, 727-100C, 727-200, and 727-200F
2019-23-16		The Boeing Company	737-100, -200, -200C, -300, -400, and -500
2019-24-12		De Havilland Aircraft of Canada Limited	DHC-8-401 and -402
2019-24-13		Airbus SAS	A318-111, -112, -121, and -122, A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-211, -212, -214, -216, -231, -232, and -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2019-24-14		328 Support Services GmbH	328-100
2019-24-15		The Boeing Company	737-900ER
2019-24-16	R 2017-16-08	Embraer S.A	ERJ 190-100 STD, -100 LR, -100 ECJ, and -100 IGW, ERJ 190-200 STD, -200 LR, and -200 IGW
2019-24-18		The Boeing Company	727, 727C, 727-100, 727-100C, 727-200, and 727-200F, 757-200, -200PF, -200CB, and -300, 767-200, -300, -300F, and -400ER
2019-25-13		Engine Alliance	GP7270 and GP7277
2019-25-17		The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER
Biweekly 2020-02			
2019-22-07		Bombardier, Inc	CL-600-2B19 (Regional Jet Series 100 & 440), CL-600-2C10 (Regional Jet Series 700, 701 & 702), CL-600-2D15 (Regional Jet Series 705), Model CL-600-2D24 (Regional Jet Series 900), Model CL-600-2E25 (Regional Jet Series 1000)
2019-23-14		The Boeing Company	37-100, -200, -200C, -300, -400, and -500
2019-24-01		Airbus SAS	A318-111, -112, -121, and -122, A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-211, -212, -214, -231, -232, and -233, A321-111, -112, -131, -211, -231, -212, -213, and -232, A330-201, -202, -203, -223, -223F, -243, and -243F, A340-211, -212, -213, -311, -312, -313, -541, and -642
2019-25-10		Fokker Services B.V	F28 Mark 0070 and 0100
2019-25-11		Viking Air Limited	CL-215-1A10, CL-215-6B11 (CL-215T Variant)
2019-25-12	R 2016-18-02	The Boeing Company	777-200 and -300ER
2019-25-14		The Boeing Company	777-300ER and 777F
2019-25-15		Fokker Services B.V	F28 Mark 0100
2019-25-16	R 2017-06-08	Embraer S.A	ERJ 170-100 LR, -100 STD, -100 SE, and -100 SU airplanes; and Model ERJ 170-200 LR, -200 SU, -200 STD, and -200 LL
2019-25-18		Bombardier, Inc	CL-600-2B19 (Regional Jet Series 100 & 440)
2019-25-19		Airbus SAS	A350-941
2020-01-11	R 2017-12-07	The Boeing Company	737-800, -900, and -900ER
2020-01-55	E	General Electric Company	GE90-110B1 and GE90-115B
Biweekly 2020-03			
2019-25-20		Lockheed Martin Corporation/Lockheed Martin Aeronautics Company	382, 382B, 382E, 382F, and 382G; C-130A, C-130B, C-130BL, C-130E, C-130H, C-130H-30, C-130J, C-130J-30, EC-130Q, HC-130H, KC-130H, NC-130B, NC-130, and WC-130H airplanes
2019-25-55		The Boeing Company	737-300, -400, and -700 series airplanes
2019-26-01		Airbus SAS	A350-941 and -1041 airplanes
2020-01-12	A 2017-16-12	Airbus SAS	A318, A319, A320, A321 airplanes
2020-01-13	R 2018-19-26	Dassault Aviation	MYSTERE-FALCON 200 airplanes
2020-01-14	A 2010-26-05	Airbus SAS	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203 airplanes
2020-01-17		Airbus SAS	A318, A319, A320, A321 airplanes
2020-01-18	R 2006-11-11	The Boeing Company	757-200, -200PF, -200CB, and -300 series airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects			
Biweekly 2020-04			
2019-26-10		Bombardier, Inc.	CL-600-2C10, -2D15, -2D25, -2E25 airplanes
2019-26-11		Airbus SAS	A319, A320, A321 airplanes
2020-01-10		Airbus SAS	A350-941 airplanes
2020-01-15		Airbus SAS	A300, A310 airplanes
2020-01-16	A 2014-25-52	Airbus SAS	A330, A340 airplanes
2020-01-55		General Electric Company	GE90-110B1 and GE90-115B model turbofan engines
2020-02-10		De Havilland Aircraft of Canada Limited	DHC-8-400, -401, and -402 airplanes
2020-02-12	R 2017-15-04	The Boeing Company	787 series airplanes
2020-02-13	R 2019-03-14 A 2010-26-05	Dassault Aviation	FAN JET FALCON, FAN JET FALCON SERIES C, D, E, F, and G airplanes
2020-02-14		Airbus SAS	A350-941 and -1041 airplanes
2020-02-15		Bombardier, Inc.	BD-700-1A10, BD-700-1A11 airplanes
2020-02-16		The Boeing Company	737-200, -200C, -300, -400, and -500 series airplanes
2020-02-18		Gulfstream Aerospace Corporation	GVI, GVII-G500, and GVII-G600 airplanes
2020-02-19	R 2003-09-04 R1	Bombardier, Inc.	CL-600-2B19 airplanes
2020-02-20	R 2014-24-07	Airbus SAS	A318, A319, A320, A321 airplanes
2020-02-21	R 2014-03-12 R 2018-19-25 A 2010-26-05	Dassault Aviation	FALCON 2000 airplanes
2020-02-22		Airbus SAS	A300, A310 airplanes
2020-03-11		The Boeing Company	707-100 long body, -200, -100B long body, -100B short body, -300, -300B, -300C, and -400 series; and 720 and 720B series airplanes
2020-03-12		Airbus SAS	A350-941 and -1041 airplanes
Biweekly 2020-05			
2020-01-18	COR R 2006-11-11	The Boeing Company	757-200, -200PF, -200CB, and -300 series airplanes
2020-02-19	COR R 2003-09-04 R1	Bombardier, Inc.	CL-600-2B19 (Regional Jet series 100 & 440) airplanes
2020-03-10		The Boeing Company	737 series, except for 737-100, -200, -200C, -300, -400, and -500 series airplanes
2020-03-14		Airbus SAS	A350-941 and -1041 airplanes
2020-03-15		Airbus SAS	A321-211, -212, -213, -231, and -232 airplanes
2020-03-17	R 2015-24-04	Bombardier, Inc.	CL-600-2B19, -2C10, -2D15, -2D25, -2E25 airplanes
2020-03-18	R 2017-19-08	Airbus Defense and Space S.A.	C-212-CB, C-212-CC, C-212-CD, C-212-CE, and C-212-DF airplanes
2020-03-19	A 2010-26-05	Dassault Aviation	MYSTERE-FALCON 20-C5, 20-D5, 20-E5, and 20-F5 airplanes
2020-03-20		The Boeing Company	MD-11, MD-11F, 717-200, 737-8, 737-9, 737-600, -700, -700C, -800, -900, and -900ER; 747-400 and 747-400F; 757-200, -200PF, -200CB, and -300; 767-200, -300, -300F, -400ER, and -2C; 777-200, -200LR, -300, and -300ER; 777F series airplanes
2020-03-21		Bombardier, Inc.	BD-700-1A10 and BD-700-1A11 airplanes
2020-03-22		The Boeing Company	787-8 airplanes
2020-03-23		Bombardier, Inc.	CL-600-2B19
2020-03-24	A 2010-26-05	Dassault Aviation	MYSTERE-FALCON 20-C5, 20-D5, 20-E5, and 20-F5 airplanes
2020-04-01		Pratt & Whitney	PW1519G, PW1521G, PW1521GA, PW1524G, PW1525G, PW1521G-3, PW1524G-3, PW1525G-3, PW1919G, PW1921G, PW1922G, PW1923G, and PW1923G-A model turbofan engines
Biweekly 2020-06			
2020-04-10	A 2011-03-10	Airbus SAS	A330 airplanes
2020-04-11		The Boeing Company	747-400 series airplanes
2020-04-12	R 2012-22-05 R 2018-19-03	Fokker Services B.V.	F28 Mark 0070 and 0100 airplanes
2020-04-18		Airbus SAS	A330-941 airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects			
2020-05-01		Rolls-Royce Deutschland Ltd & Co KG	Trent 1000-AE3, Trent 1000-CE3, Trent 1000-D3, Trent 1000-G3, Trent 1000-H3, Trent 1000-J3, Trent 1000-K3, Trent 1000-L3, Trent 1000-M3, Trent 1000-N3, Trent 1000-P3, Trent 1000-Q3, and Trent 1000-R3 model turbofan engines
2020-05-10		Dassault Aviation	FALCON 7X airplanes
2020-05-12		Gulfstream Aerospace Corporation	GVII-G500 and GVII-G600 airplanes
2020-05-13		Airbus Canada Limited Partnership	BD-500-1A11 airplanes
2020-05-14		Airbus SAS	A320-214, -232, -271N; A321-231 airplanes
2020-05-18		Airbus SAS	A350-941 and -1041 airplanes
2020-06-01	R 2018-25-09 R 2019-12-01	CFM International, S.A.	LEAP-1B21, -1B23, -1B25, -1B27, -1B28, -1B28B1, -1B28B2, -1B28B3, -1B28B2C, -1B28BBJ1, and -1B28BBJ2 model turbofan engines
Biweekly 2020-07			
2020-04-19	R 2017-15-01	The Boeing Company	777-200, -200LR, -300, -300ER, and 777F series airplanes
2020-05-13		Airbus Canada Limited Partnership	BD-500-1A11 airplanes
2020-05-14		Airbus SAS	A320-214, -232, -271N; A321-231 airplanes
2020-05-15		Airbus SAS	A319-131, -132, -133; A320-231, -232, -233; and A321-131, -231, -232 airplanes
2020-05-16		Airbus SAS	A319-115; A320-214, -216, -232, -251N, -271N; and A321-211, -231, -251N, -251NX, -253N, -271N, -271NX, -272N airplanes
2020-05-17		Airbus SAS	A318-112, A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A320-211, A320-212, A320-214, A320-216, A320-231, A320-232, A320-233, A320-251N, and A320-271N airplanes
2020-05-18		Airbus SAS	A350-941 and -1041 airplanes
2020-05-19		Airbus SAS	A319-112, -115, -132; and A320-214, -216, -232 -233 airplanes
2020-05-21		Yaborã Indústria Aeronáutica S.A.	ERJ 190-100 STD, -100 LR, -100 ECJ, -100 IGW, -200 STD, -200 LR, and -200 IGW airplanes
2020-05-22		Yaborã Indústria Aeronáutica S.A.	ERJ 170-100 LR, -100 STD, -100 SE, -100 SU; and ERJ 170-200 LR, -200 SU, -200 STD, -200 LL airplanes
2020-05-24	R 2010-26-01	The Boeing Company	777-200 series airplanes
2020-05-28	R 2019-11-08	International Aero Engines LLC	PW1133G-JM, PW1133GA-JM, PW1130G-JM, PW1129G-JM, PW1127G-JM, PW1127GA-JM, PW1127G1-JM, PW1124G-JM, PW1124G1-JM, and PW1122G-JM turbofan engines
2020-06-02		International Aero Engines LLC	PW1122G-JM, PW1124G1-JM, PW1124G-JM, PW1127GA-JM, PW1127G1-JM, PW1127G-JM, PW1133G-JM, PW1133GA-JM, PW1130G-JM, and PW1129G-JM turbofan engines
2020-06-14		The Boeing Company	787-8, 787-9, and 787-10 airplanes
2020-07-51	E	International Aero Engines AG	V2522-A5, V2524-A5, V2525-D5, V2527-A5, V2527E-A5, V2527M-A5, V2528-D5, V2530-A5, and V2533-A5 turbofan engines
Biweekly 2020-08			
2020-04-15		The Boeing Company	757-200, -200PF, -200CB, and -300 series; 767-200, -300, and -300F series airplanes
2020-04-16		Yaborã Indústria Aeronáutica S.A.	ERJ 190-100 STD, -100 LR, -100 IGW, -200 STD, -200 LR, and -200 IGW airplanes
2020-04-17		Airbus SAS Model	A350-941 and -1041 airplanes
2020-04-20		De Havilland Aircraft of Canada Limited	DHC-8-400, -401, and -402 airplanes
2020-04-22	R 2018-19-27 R 2014-16-12 A 2010-26-05	Dassault Aviation	FALCON 2000EX airplanes
2020-05-25		The Boeing Company	757-200, -200PF, -200CB, and -300 series airplanes
2020-05-26		The Boeing Company	787-8 airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects			
2020-05-27 2020-06-10		Bombardier, Inc. Airbus SAS	BD-700-1A10 and BD-700-1A11 airplanes A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -216, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes
2020-06-15 2020-06-16	R 2017-03-02	Fokker Services B.V. Rolls-Royce Deutschland Ltd. & Co. KG	F28 Mark 0100 airplanes RB211 Trent 768-60, 772-60, and 772B-60 turbofan engines
2020-06-17	R 2011-09-06	Airbus SAS	A330-223F and -243F; A330-201, -202, -203, -223, and -243; A330-301, -302, -303, -321, -322, -323, -341, -342, and -343; A330-941; A340-211, -212, and -213; A340-311, -312, and -313; A340-541 and -642 airplanes
2020-06-18		Airbus SAS	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, -133, -151N, -153N, and -171N; A320-211, -212, -214, -216, -231, -232, -233, -251N, -252N, -253N, -271N, -272N, and -273N; A321-111, -112, -131, -211, -212, -213, -231, -232, -251N, -251NX, -252N, -252NX, -253N, -253NX, -271N, -271NX, -272N, and -272NX airplanes
2020-07-02		Pratt & Whitney	PW1519G, PW1521G, PW1521G-3, PW1521GA, PW1524G, PW1524G-3, PW1525G, and PW1525G-3 turbofan engines
2020-07-10 2020-08-01		Airbus SAS General Electric Company	A320-271N; A321-271N, -271NX, and -272N airplanes CF34-1A, CF34-3A, CF34-3A1, CF34-3A2, CF34-3B, and CF34-3B1 turbofan engines
Biweekly 2020-09			
2020-07-11		ATR–GIE Avions de Transport Regional	ATR42-200, -300, -320, and -500; ATR72-101, -102, -201, -202, -211, -212, and -212A
2020-07-12		ATR–GIE Avions de Transport Regional	ATR42-500
2020-07-13 2020-07-14		Bombardier, Inc The Boeing Company	BD-100-1A10 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series
2020-07-16	R 2016-16-09 R 2019-03-20 A 2014-16-23	Dassault Aviation	FALCON 7X
2020-07-17 2020-07-18	R 2017-05-12	Saab AB, Support and Services Airbus SAS	SAAB 2000 A318-112; A319-111, -112, -115, -132, and -133; A320-214, -216, -232, and -233; A321-211, -212, -213, -231, and -232
2020-07-19		ATR–GIE Avions de Transport Regional	ATR72-101, -102, -201, -202, -211, -212, and -212A
2020-07-20	R 2004-06-01 R 2009-06-09 A 2008-17-01 R1 A 2012-01-08	Support Services GmbH	328-100
2020-07-21		Yabora Industria Aeronautica S.A.	ERJ 170-100 LR, -100 STD, -100 SE, and -100 SU; ERJ 170-200 LR, -200 SU, -200 STD, and -200 LL; ERJ 190-100 STD, -100 LR, -100 ECJ, -100 IGW, -200 STD, -200 LR, and -200 IGW
2020-07-51		International Aero Engines AG	V2522-A5, V2524-A5, V2525-D5, V2527-A5, V2527E-A5, V2527M-A5, V2528-D5, V2530-A5, and V2533-A5
2020-08-02		Thales AVS France SAS	Global Positioning System/Satellite Based Augmentation System receivers
2020-08-03	R 2008-22-24	Rolls-Royce Deutschland Ltd & Co KG	RB211-535E4-37, RB211-535E4-B-37, RB211-535E4-C-37, and RB-211-535E4-B-75
2020-08-04		International Aero Engines LLC	PW1133G-JM, PW1133GA-JM, PW1130G-JM, PW1129G-JM, PW1127G-JM, PW1127GA-JM, PW1127G1-JM, PW1124G-JM, PW1124G1-JM, and PW1122G-JM
2020-09-03		International Aero Engines AG	V2500-A1, V2522-A5, V2524-A5, V2525-D5, V2527-A5, V2527E-A5, V2527M-A5, V2528-D5, V2530-A5, V2531-E5, and V2533-A5

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects

Biweekly 2020-10

2020-08-11		Yabora Industria Aeronautica S.A.	ERJ 190-300 and ERJ 190-400
2020-08-12		The Boeing Company	747-8 and 747-8F series
2020-08-13		Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440); CL-600-2C10 (Regional Jet Series 700, 701 & 702); CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900)



AIRWORTHINESS DIRECTIVE

2020-08-11 Yabora Industria Aeronautica S.A. (Type Certificate previously held by Embraer S.A.): Amendment 39-19903; Docket No. FAA-2020-0340; Product Identifier 2019-NM-203-AD.

(a) Effective Date

This AD becomes effective May 22, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Yabora Industria Aeronautica S. A. (Type Certificate previously held by Embraer S.A.) Model ERJ 190-300 and ERJ 190-400 airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 24, Electrical power.

(e) Reason

This AD was prompted by a failure propagation test, which revealed that when complete loss of the electrical digital current (DC) essential bus 2 was induced the smoke detection system of the forward and aft electrical bays erroneously indicated the presence of smoke via the respective engine indication and crew alerting system (EICAS) messages. The FAA is issuing this AD to provide the flightcrew with revised airplane flight manual (AFM) procedures for responding to erroneous indications of smoke in the electrical bays presented on the EICAS. If the flightcrew followed the existing AFM procedures, it could result in a loss of all electrical DC essential buses, causing loss of electrical power for critical systems of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, Agência Nacional de Aviação Civil (ANAC) Brazilian Emergency Airworthiness Directive (EAD) 2019-12-01, effective December 9, 2019 (“Brazilian EAD 2019-12-01”).

(h) Exceptions to Brazilian EAD 2019-12-01

(1) Where Brazilian EAD 2019-12-01 refers to its effective date, this AD requires using the effective date of this AD.

(2) The “Alternative method of compliance (AMOC)” section of Brazilian EAD 2019-12-01 does not apply to this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the Large Aircraft Section, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or ANAC; or ANAC's authorized Designee. If approved by the ANAC Designee, the approval must include the Designee's authorized signature.

(j) Related Information

For more information about this AD, contact Krista Greer, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3223; email krista.greer.@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Agência Nacional de Aviação Civil National Civil Aviation Agency (ANAC) Brazilian Emergency Airworthiness Directive (EAD) 2019-12-01, effective December 9, 2019.

(ii) [Reserved]

(3) For information about ANAC Brazilian EAD 2019-12-01, contact National Civil Aviation Agency, Aeronautical Products Certification Branch (GGCP), Rua Laurent Martins, n° 209, Jardim Esplanada, CEP 12242-431–São José dos Campos–SP, Brazil; telephone 55 (12) 3203-6600; email pac@anac.gov.br; internet www.anac.gov.br/en/.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0340.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on April 23, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-09633 Filed 5-6-20; 8:45 am]



2020-08-12 The Boeing Company: Amendment 39-19904; Docket No. FAA-2020-0095; Product Identifier 2019-NM-192-AD.

(a) Effective Date

This AD is effective June 2, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 747-8 and 747-8F series airplanes, certificated in any category, as identified in Boeing Alert Requirements Bulletin 747-53A2895 RB, dated September 12, 2019.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by an evaluation by the design approval holder (DAH) indicating that the skin lap joints at certain stringers are subject to widespread fatigue damage (WFD). The FAA is issuing this AD to address undetected fatigue cracks, which could result in sudden decompression and reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified by paragraph (h) of this AD: At the applicable times specified in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 747-53A2895 RB, dated September 12, 2019, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 747-53A2895 RB, dated September 12, 2019.

Note 1 to paragraph (g): Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 747-53A2895, dated September 12, 2019, which is referred to in Boeing Alert Requirements Bulletin 747-53A2895 RB, dated September 12, 2019.

(h) Exception to Service Information Specifications

Where Boeing Alert Requirements Bulletin 747-53A2895 RB, dated September 12, 2019, specifies contacting Boeing for repair instructions: This AD requires doing the repair before further flight using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(j) Related Information

(1) For more information about this AD, contact Bill Ashforth, Senior Aerospace Engineer, Airframe Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3520; email: bill.ashforth@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (k)(3) and (4) of this AD.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 747-53A2895 RB, dated September 12, 2019.

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on April 20, 2020.

Gaetano A. Sciortino,
Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft
Certification Service.

[FR Doc. 2020-08930 Filed 4-27-20; 8:45 am]



FAA
Aviation Safety

AIRWORTHINESS DIRECTIVE

www.faa.gov/aircraft/safety/alerts/
www.gpoaccess.gov/fr/advanced.html

2020-08-13 Bombardier, Inc.: Amendment 39-19905; Docket No. FAA-2020-0092; Product Identifier 2020-NM-001-AD.

(a) Effective Date

This AD is effective June 10, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc. airplanes, certificated in any category, as specified in paragraphs (c)(1) through (4) of this AD.

(1) Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes, serial numbers (S/Ns) 7003 through 7990 inclusive, and S/Ns 8000 and subsequent.

(2) Model CL-600-2C10 (Regional Jet Series 700, 701 & 702) airplanes, S/Ns 10002 through 10347 inclusive.

(3) Model CL-600-2D15 (Regional Jet Series 705) airplanes and Model CL-600-2D24 (Regional Jet Series 900) airplanes, S/Ns 15001 through 15469 inclusive.

(4) Model CL-600-2C11 (Regional Jet Series 550) airplanes, all serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight controls.

(e) Reason

This AD was prompted by reports of fractured rudder primary feel unit shafts; a subsequent investigation determined that the fractures in the shafts are consistent with fatigue damage. The FAA is issuing this AD to address fractures of the rudder primary feel unit shaft, which could result in a loss of feel in the yaw axis and thereby impact the controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Replacement

Within the compliance times specified in figure (1) to paragraph (g) of this AD: Replace all rudder primary feel unit shafts that have part number (P/N) 600-90251-1 with a new shaft, in accordance with the Accomplishment Instructions of the Bombardier Service Bulletin 601R-27-166, dated April 5, 2019; or Bombardier Service Bulletin 670BA-27-075, dated April 5, 2019; as

applicable. For Model CL-600-2C11 (Regional Jet Series 550) airplanes, do the replacement in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 670BA-27-075, dated April 5, 2019.

Figure 1 to paragraph (g) – Compliance Times

Accumulated Airplane Flight Cycles	Compliance Time for the Replacement
For airplanes that have accumulated 22,000 total flight cycles or less as of the effective date of this AD.	Before the airplane reaches 30,000 total flight cycles.
For airplanes that have accumulated more than 22,000 total flight cycles, but less than 37,000 total flight cycles, as of the effective date of this AD.	Within 8,000 flight cycles from the effective date of this AD.
For airplanes that have accumulated 37,000 total flight cycles or more, but less than 40,000 total flight cycles, as of the effective date of this AD.	Before the airplane reaches 45,000 total flight cycles.
For airplanes that have accumulated 40,000 total flight cycles or more, but less than 46,500 total flight cycles, as of the effective date of this AD.	Within 5,000 flight cycles from the effective date of this AD.
For airplanes that have accumulated 46,500 total flight cycles or more as of the effective date of this AD.	Before the airplane reaches 51,500 total flight cycles.

(h) Parts Installation Prohibition

As of the effective date of this AD, no person may install a rudder primary feel unit shaft, P/N 600-90251-1, on any airplane.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian AD CF-2019-42, dated November 8, 2019, for related information. This MCAI may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0092.

(2) For more information about this AD, contact Andrea Jimenez, Aerospace Engineer, Airframe and Mechanical Systems Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7330; fax 516-794-5531; email 9-avs-nyaco-cos@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 601R-27-166, dated April 5, 2019.

(ii) Bombardier Service Bulletin 670BA-27-075, dated April 5, 2019.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; Widebody Customer Response Center North America toll-free telephone 1-866-538-1247 or direct-dial telephone 1-514-855-2999; fax 514-855-7401; email ac.yul@aero.bombardier.com; internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on April 20, 2020.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-09663 Filed 5-5-20; 8:45 am]