


SPECIAL AIRWORTHINESS INFORMATION BULLETIN



U.S. Department
of Transportation
**Federal Aviation
Administration**

AIRCRAFT CERTIFICATION SERVICE
800 INDEPENDENCE AVENUE, S.W.
WASHINGTON, DC 20591

No. ACE-99-04
November 6, 1998

Published by: FAA, AFS-610, P.O. Box 26460, Oklahoma City, OK 73125

This is issued for informational purposes only and any recommendation for corrective action is not mandatory.

Introduction

The purpose of this Special Airworthiness Information Bulletin (SAIB) is to advise owners/operators of Avions Robin (Avions Pierre Robin) R2160 airplanes of the need to review the service bulletins listed below.

Background

The Small Airplane Directorate, Aircraft Certification Service, of the Federal Aviation Administration (FAA) conducted a review of specified Avions Robin (Avions Pierre Robin) R2160 airplane service bulletins. The purpose of the review was to evaluate each service bulletin to determine the continued airworthiness safety aspect. The options considered by the FAA included: mandated compliance by initiation of an FAA Airworthiness Directive (AD), various forms of notices, or no further action required.

Owners/operators of Avions Robin (Avions Pierre Robin) R2160 airplanes should also note that there have been Airworthiness Directives issued against these airplanes concerning other safety issues.

Recommendation

The service bulletins identified in this document were not considered appropriate for AD action at this time, however, the FAA strongly suggests that all owners/operators of the Avions Robin (Avions Pierre Robin) R2160 airplanes review their compliance with the service bulletins listed below.

Service Bulletin

Number	DATE	TITLE
75	04/11/78	Replacement of 3-Rib Flaps
93	07/06/87	Flap Motor Reduction Gear
114	01/29/92	Quick-disconnect Link Between the Frame and the Safety Belts or Harnesses
155	10/09/97	Use in Utility Category of R2160 Aircraft

The service bulletins can be obtained from:

Avions Robin
1, route de Troyes
21121 Darois
France

FAX: 011 33 (0)3 80 35 60 80
PHONE: 011 33 (0)3 80 44 20 50

For Further Information Contact:

Karl M. Schletzbaum, Aerospace Engineer, FAA, Project Support Branch (ACE-112), Small Airplane Directorate, 601 E. 12th Street, Kansas City, Missouri, 64106, telephone (816) 426-6934.