


SPECIAL AIRWORTHINESS INFORMATION BULLETIN



U.S. Department
of Transportation
**Federal Aviation
Administration**

AIRCRAFT CERTIFICATION SERVICE
800 INDEPENDENCE AVENUE, S.W.
WASHINGTON, DC 20591

No. ACE-99-09
December 2, 1998

Published by: FAA, AFS-610, P.O. Box 26460, Oklahoma City, OK 73125

This is issued for informational purposes only and any recommendation for corrective action is not mandatory.

Introduction

The purpose of this Special Airworthiness Information Bulletin is to advise operators of Dornier Model 28 airplanes of the need to review the service information listed below.

Background

The Small Airplane Directorate, Aircraft Certification Service, of the Federal Aviation Administration (FAA) conducted a review of specified Dornier Model 27 and 28 airplanes service bulletins. The purpose of the review was to evaluate each service bulletin to determine the continued airworthiness safety aspect. The options considered by the FAA included: mandated compliance by initiation of an FAA Airworthiness Directive (AD), various forms of notices, or no further action required.

Owners/operators of Dornier Model 27 and 28 airplanes should also note that there have been Airworthiness Directives issued against these airplanes concerning other safety issues.

Recommendations

The service information identified in this document is not considered appropriate for AD action at this time, however, the FAA strongly suggests that all owners/operators of the Dornier Model 28 airplanes review their compliance with the service information listed below.

Dornier Model 28 Airplane Series Service Bulletin Number	MODEL	DATE	SUBJECT
1084-2820	DO28D-1	11/21/83	Pitch, pitch trim, rudder, and roll actuators
1090-1107	DO28D, DO28D-1	11/21/83	Wing trailing edge structure
1094-2401	DO28D, DO28D-1	11/21/83	Cockpit flight controls
1113-3829	DO28D-1	04/8/87	Auxiliary fuel tank mounting fitting
1114-3405	DO28D, DO28D-1	05/8/87	Flap actuator rod end
1115-2603	DO28D, DO28D-1	07/10/87	Precautionary engine shutdown procedures

The service information document can be obtained from:

Dornier Luftfahrt GmbH
Customer Support
P.O. Box 1103
D-82230 Wessling
Germany
Phone: (08153) 300
Fax: (08153) 302985

FOR FURTHER INFORMATION CONTACT:

Karl Schletzbaum, Aerospace Engineer, FAA, Project Support Branch (ACE-112), Small Airplane Directorate, 1201 Walnut, Suite 900, Kansas City, Missouri 64106, telephone (816) 426-6934.