


SPECIAL AIRWORTHINESS INFORMATION BULLETIN



U.S. Department
of Transportation
**Federal Aviation
Administration**

AIRCRAFT CERTIFICATION SERVICE
800 INDEPENDENCE AVENUE, S.W.
WASHINGTON, DC 20591

No. ACE-98-34
June 4, 1998

Published by: FAA, AFS-610, P.O. Box 26460, Oklahoma City, OK 73125

This is issued for informational purposes only and any recommendation for corrective action is not mandatory.

Introduction

The purpose of this Special Airworthiness Information Bulletin is to advise owners/operators of Avions Mudry et Cie CAP 10B airplanes of the need to review the service bulletins listed below.

Background

The Small Airplane Directorate, Aircraft Certification Service, of the Federal Aviation Administration (FAA) conducted a review of specified Avions Mudry et Cie CAP 10B airplane service bulletins. The purpose of the review was to evaluate each service bulletin to determine the continued airworthiness safety aspect. The options considered by the FAA included: mandated compliance by initiation of an FAA Airworthiness Directive (AD), various forms of notices, or no further action required.

Owners/operators of Avions Mudry et Cie CAP 10B airplanes should also note that there have been Airworthiness Directives issued against these airplanes concerning other safety issues.

Recommendations

The service bulletins identified in this document were not considered appropriate for AD action at this time, however, the FAA strongly suggests that all owners/operators of the Avions Mudry et Cie CAP 10B airplanes review their compliance with the service bulletins listed below.

Mudry Service Bulletin Number	DATE	TITLE
1	7/5/77	Attachment Bracket of the Inter Legs Belt of Aerobatics Harness
2	7/20/77	Cracks on the Skin of the Lower Surface of the Wing; Tightening of Bolts in the Wood; Release of the Rear End of the Elevator Cable
4	11/17/77	Engine Mount 70.01.00 A or E
6	4/4/79	Stick Boots
11	10/10/88	Rudder Control Lever Inspection

The Service Bulletins Can Be Obtained From:

Avions Mudry et Cie,
c/o Akrotech
9, route de l'Aviation
21121 Darois, France

Telephone: 01-33-03-8035-6510

For Further Information Contact:

Karl M. Schletzbaum, Aerospace Engineer, FAA, Project Support Branch (ACE-112), Small Airplane Directorate, 601 E. 12th Street, Kansas City, Missouri, 64106, telephone (816) 426-6934, fax (816) 426-2169.