


SPECIAL AIRWORTHINESS INFORMATION BULLETIN



U.S. Department
of Transportation
**Federal Aviation
Administration**

AIRCRAFT CERTIFICATION SERVICE
800 INDEPENDENCE AVENUE, S.W.
WASHINGTON, DC 20591

No. ACE-98-28
April 24, 1998

Published by: FAA, AFS-610, P.O. Box 26460, Oklahoma City, OK 73125

This is issued for informational purposes only and any recommendation for corrective action is not mandatory.

Introduction

The purpose of this Special Airworthiness Information Bulletin is to advise owners/operators of SIAI Marchetti S205 and S208 series aircraft of the need to review the service bulletins listed below.

Background

The Small Airplane Directorate, Aircraft Certification Service, of the Federal Aviation Administration (FAA) conducted a review of specified SIAI Marchetti airplane service bulletins. The purpose of the review was to evaluate each service bulletin to determine the continued airworthiness safety aspect. The options considered by the FAA included: mandated compliance by initiation of an FAA Airworthiness Directive (AD), various forms of notices, or no further action required.

Recommendation

The service bulletins identified in this document were not considered appropriate for AD action at this time, however, the FAA strongly suggests that all owners/operators of the specified SIAI Marchetti S205 and S208 series aircraft review their compliance of the service bulletins listed below.

Service Bulletin No.	Date	Title
205B48 Rev. F	October 7, 1977	Inspection of Main Landing Gear Assembly
205B49 Rev B	May 28, 1993	Cracking of Main Landing Gear Dampers
205-SB-061	December 1, 1997	Periodic inspections of sheaths protecting engine control cables

The Service Bulletin Information can be Obtained From:

SIAI Marchetti
Via Indipendenza 2
21018 Varese - ITALY

For Further Information Contact:

Dave Keenan, Aerospace Engineer, FAA, Project Support Branch (ACE-112), Small Airplane Directorate, 601 East 12 Street, Kansas City, Missouri, 64106; telephone: (816) 426-6934; facsimile: (816) 426-2169.