

United States of America  
Department of Transportation -- Federal Aviation Administration  
**Supplemental Type Certificate**

*Number* SA2-543

*This certificate, issued to* Rockwell Collins, Inc.  
400 Collins Road NE, MS 164-100  
Cedar Rapids, IA 52498

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 4b of the Civil Air Regulations.*

*Original Product - Type Certificate Number :* 6A6  
*Make :* Convair  
*Model :* 440

*Description of Type Design Change:*

Aircraft Modification and Installation of Collins Autopilot made in accordance with Collins Radio Company Drawing 562-6900-004 and drawings called out thereon dated 3-1-58.

NOTE: Collins Radio Company CAA Approved Airplane Flight Manual Supplement, dated June 17, 1958, to Convair 400 Airplane Flight Manual, required with this modification.

*Limitations and Conditions:*

Compatibility of this design change with previously approved modifications must be determined by the installer. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application :* May 22, 1958

*Date reissued :* June 25, 1999, April 24, 2000

*Date of issuance :* June 17, 1958

*Date amended :* November 06, 1958



*By direction of the Administrator*

*Dale R. Koonts*  
(Signature)

Dale R. Koonts

Manager, DAS-3CE

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 1 year, or both.