

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number SR09477RC

This certificate issued to

Keystone Helicopter Corporation
110 E. Stewart Huston Drive
Coatesville, PA 19320

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 29 of the Regulations.

Original Product -- Type Certificate Number: R00024B0
Make: Sikorsky Aircraft Corporation
Model: S-92A

Description of Type Design Change: Installation of Electronic Standby Instrument System (ESIS) for the Sikorski Model S-92 helicopter, in accordance with Heritage Aviation Ltd. Master Drawing List, Drawing Number S00-14001, Revision IR, dated November 6, 2006 or later FAA approved revision. Rotorcraft Flight Manual Supplement dated January 19, 2007 or later FAA approved revision is required. Instructions for Continued Airworthiness, Heritage Aviation Ltd. Document Number S04-74000, accepted June 7, 2006, or later accepted revision is required.

Limitations and Conditions:

Compatibility of this design change with previously approved modifications must be determined by the installer. If the holder agrees to permit another person to use this certificate to alter a product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: November 21, 2005

Date reissued: June 04, 2009

Date of issuance: January 18, 2007

Date amended:



By direction of the Administrator

(Signature)
Lance T. Gant, Manager
Rotorcraft Certification Office
Southwest Region

(Title)

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate
(Continuation Sheet)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.